

IN THE SPECIFICATION:

Please replace the paragraph beginning on line 15 of page 7 and ending on line 2 of page 8 with the following rewritten paragraph:

As best shown in Figure 6, another opening 66 in one of the side walls 40, 42 of the upper channel 118 has the nozzle 64 received therein. The nozzle [[64]] 68 is fixed in the opening 66 of the upper channel 118 such that the nozzle [[64]] 68 is maintained in sealing engagement with the opening 66. The nozzle 64 has a through hole [[68]] 69 that is formed to dispense wiper fluid from the upper channel 118 such that the wiper fluid exits preferably in a desired spray pattern. The nozzle [[64]] 68 is shown here to be generally equidistant between the two ends 24, 26 of the upper channel 118. It should be recognized however, that the opening 66 used to receive the nozzle [[64]] 68 can be placed anywhere along the length between the two ends 24, 26 of the upper channel 118, as best suited for the application. It should also be recognized that any number of nozzles [[64]] 68 can be employed within the sidewalls 140, 142 to insure adequate coverage of wiper fluid on the surface to be wiped by the wiper blade assembly 110.